DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING

1594 West North Temple, Suite 1210

Kathleen Clarke **Executive Director**

Governor

Michael O. Leavitt

Lowell P. Braxton Division Director PO Box 145801 Salt Lake City, Utah 84114-5801

801-538-5340 801-359-3940 (Fax) 801-538-7223 (TDD)

INSPECTION REPORT

Partial: XXX_	Complete:	Exploration:	4
Inspection I	Date & Time:	11/20/00 / 10:50 am-1 p	m
	t Inspection: _		

Mine Name: Trail Mountain Mine County: Emery	Permit Number: Costs/009
Permittee and/or Operator's Name: PacifiCorp	
Business Address: P.O. Box 310, Huntington, Utah 84528	
Type of Mining Activity: Underground XXX Surface	Prep. Plant Other
Company Official(s): Mr. Dennis Oakley, Environmental Engine	er
State Official(s): Peter Hess, Rec Spec III Federal Official(s):	
Weather Conditions: Sunny, Clear/40's Fahrenheit	
Existing Acreage: Permitted 4178 Disturbed 10.7 Reg	graded Seeded
Status: Active XXX	

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

- Substantiate the elements on this inspection by checking the appropriate performance standard.
 - For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - For partial inspections check only the elements evaluated.
- Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below. 2.
- Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below. 3.
- Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

		EVALUATED	<u>N/A</u>	COMMENTS	NOV/ENF
1.	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE		\Box	П	\Box
2.	SIGNS AND MARKERS	[X]	\Box		\Box
3.	TOPSOIL	[X]	\Box	\Box	\Box
4.	HYDROLOGIC BALANCE:				
	a. DIVERSIONS	[X]	\Box	[X]	\Box
	b. SEDIMENT PONDS AND IMPOUNDMENTS		\Box		П
	c. OTHER SEDIMENT CONTROL MEASURES	\Box	\Box		Ц
	d. WATER MONITORING	\Box	\Box	П	Ц
	e. EFFLUENT LIMITATIONS		\Box	\Box	Ц
5.	EXPLOSIVES		\Box	Ц	Ц
6.	DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES		[X]	П	Ц
7.	COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	[X]	\Box	[X]	Ц
8.	NONCOAL WASTE	[X]	П	[X]	П
9.	PROTECTION OF FISH, WILDLIFE AND RELATED	П	\Box	П	\Box
	ENVIRONMENTAL ISSUES				.
10.	SLIDES AND OTHER DAMAGE		[X]	П	П
	CONTEMPORANEOUS RECLAMATION	П	[X]	. 🗓	П
	BACKFILLING AND GRADING	Ш	[X]	Ц	
	REVEGETATION	\Box	[X]	Ц	Ц
14.	SUBSIDENCE CONTROL	П	П	· <u>[</u>]	Ц
15.	CESSATION OF OPERATIONS		\Box	П	\Box
16.	ROADS:				
	a. CONSTRUCTION/MAINTENANCE/SURFACING	[X]	Ц	Ц	
	b. DRAINAGE CONTROLS	[X]	Ц	<u> </u>	
	OTHER TRANSPORTATION FACILITIES		Ц	П	П
	SUPPORT FACILITIES/UTILITY INSTALLATIONS	[X]	Ц	Ц	
	AVS CHECK (4th Quarter- April, May, June)	Ц	Ц	Ц	
	AIR QUALITY PERMIT	Ц	П	Ц	
21.	BONDING & INSURANCE		\Box		П

INSPECTION REPORT

(Continuation sheet)

PERMIT NUMBER: <u>C/015/009</u>

DATE OF INSPECTION: <u>11/20/2000</u>

(COMMENTS ARE NUMBERED TO CORRESPOND WITH TOPICS LISTED ABOVE)

4A. HYDROLOGIC BALANCE: DIVERSIONS

The permittee has repaired both of the erosion features which were adjacent to the shallow concrete inlet ditch reporting to the sediment pond. These were noted during the October inspection.

7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS

The mine site area has a small area permitted for the temporary storage of mine development waste. Material was noted this day. The permanent disposal of the material takes place at the Cottonwood waste rock site. Nielsen Construction is under contract to haul the material on an as needed basis.

8. NONCOAL WASTE

The southwest corner of the asphalt parking lot (adjacent to the bath house trailer) had numerous items of food wrapping materials (cups, soda cans, potato chip bags, etc.) lying on the paved surface. The garbage can in the immediate area was filled to over capacity; the material on the ground may have been dispersed by high velocity winds. Mr. Oakley immediately contacted the Mine's surface foreman to report the problem. The garbage was picked up before the end of today's inspection.

There were several empty lubricant containers (55 gallon) noted about the dumpster just north of the mine site sediment pond. One drum was lying on its side; same was stood up. All of the empty barrels had their bungs in place. There were no lubricant leaks noted from any of the drums. It was suggested to the surface foreman that extra drums be crushed and removed.

As a minimal precaution, the permittee should store the empty barrels in a central location.

Inspector's Signature:

Peter Hess #4

Date: November 20, 2000

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas & Mining.

sd

cc: James Fulton, OSM

Chuck Semborski, PacifiCorp

Price Field office

O:\015009.TMT\Compliance\2000\p 1120.wpd